Specifications



# Front bottom connection, MasterPact MTZ2 fixed, 4P, 800A-1600A, spare part

LV847933SP

#### Main

IVIAIII	
Range	MasterPact
Type Of Accessory	Connection accessory
Product Or Component Type	Front connection
Poles Description	4P
Complementary	

Complementary	/
Product Compatibility	MasterPact MTZ2 08-12 N1
	MasterPact MTZ2 06-16 H1
	MasterPact MTZ2 06-16 H2
	MasterPact MTZ2 06-10 L1
	MasterPact MTZ2 16 H1T
	MasterPact MTZ2 08-16 N2
Mounting Mode	Fixed
Connection Accesibility	Front
Position On Device	Downside
Connection Pitch	115 mm
Provided Equipment	1 instruction sheet
Offer Type	Spare part

# **Packing Units**

Unit Type Of Package 1	PCE
Number Of Units In Package 1	1
Package 1 Height	12.300 cm
Package 1 Width	13.300 cm
Package 1 Length	19.000 cm
Package 1 Weight	3.400 kg
Unit Type Of Package 2	\$03
Number Of Units In Package 2	4
Package 2 Height	30.000 cm
Package 2 Width	30.000 cm
Package 2 Length	40.000 cm
Package 2 Weight	13.600 kg

### **Sustainability**

**Green Premium<sup>TM</sup> label** is Schneider Electric's commitment to delivering products with best-inclass environmental performance. Green Premium promises compliance with the latest regulations, transparency on environmental impacts, as well as circular and low-CO<sub>2</sub> products.

**Guide to assessing product sustainability** is a white paper that clarifies global eco-label standards and how to interpret environmental declarations.

Learn more about Green Premium >

Guide to assess a product's sustainability >

#### Well-being performance

Reach Free Of Svhc	
Toxic Heavy Metal Free	
Mercury Free	
Rohs Exemption Information	Yes
Reach Regulation	REACh Declaration
Eu Rohs Directive	Pro-active compliance (Product out of EU RoHS legal scope) EU RoHS Declaration
China Rohs Regulation	China RoHS declaration Pro-active China RoHS declaration (out of China RoHS legal scope)
California Proposition 65	WARNING: This product can expose you to chemicals including: DINP, which is known to the State of California to cause cancer, and DIDP, which is known to the State of California to cause birth defects or other reproductive harm. For more information go to www.P65Warnings.ca.gov