

# SinCos Hiperface encoder cable between servomotor BRH, BSH and LXM05 - 20 m

VW3M8101R200

### ! Discontinued

### Main

Accessory / Separate Part Designation	SinCos Hiperface encoder cable	
Accessory / Separate Part Type	Connecting cable	
Accessory / Separate Part Category	Connection accessories	
Product Compatibility	BSH all ratings BRH all ratings LXM05 all ratings	
Accessory / Separate Part Destination	Between servo motor and servo drive	
Range Compatibility	Lexium 05	
Cable Length	20 m	
Cable Composition	5 x (2 x 0.25 mm²) + (2 x 0.5 mm²)	

# Complementary

Electrical Connection	1 connector 12-way female Molex (servo drive side) 1 connector industrial M23 (servo motor side)
Net Weight	4.35 kg

### **Contractual warranty**

Warranty 18 months

## Sustainability

**Green Premium<sup>TM</sup> label** is Schneider Electric's commitment to delivering products with best-inclass environmental performance. Green Premium promises compliance with the latest regulations, transparency on environmental impacts, as well as circular and low-CO<sub>2</sub> products.

**Guide to assessing product sustainability** is a white paper that clarifies global eco-label standards and how to interpret environmental declarations.

Learn more about Green Premium >

Guide to assess a product's sustainability >





Transparency RoHS/REACh

# Well-being performance

<b>Ø</b>	Reach Free Of Svhc			
<b>⊘</b>	Toxic Heavy Metal Free			
<b>⊘</b>	Mercury Free			
<b>⊘</b>	Rohs Exemption Information	Yes		
<b>⊘</b>	Pvc Free			

### **Certifications & Standards**

Reach Regulation	REACh Declaration
Eu Rohs Directive	Pro-active compliance (Product out of EU RoHS legal scope) EU RoHS Declaration
China Rohs Regulation	China RoHS declaration
Environmental Disclosure	Product Environmental Profile
Circularity Profile	End of Life Information
California Proposition 65	WARNING: This product can expose you to chemicals including: Lead and lead compounds, which is known to the State of California to cause cancer and birth defects or other reproductive harm. For more information go to www.P65Warnings.ca.gov