

## End of Life Notification – APC Rack Mount PDU 7000 Series

Dear customer,

APC By Schneider Electric is dedicated to providing products with the latest security protocols to our customers. Recently, we have transitioned our 7000 series Rack Mount PDUs to a new Network Management Card with TLS 1.2 security support. Due to the change in Management Card, any existing customer test scripts or commands may need to be evaluated or modified.

The transition took place in January 2017 with a full release of the “B” part numbers.

-----

The list of part numbers that have been transitioned are the following:

AP7152, AP7155, AP7175, AP7800, AP7801, AP7802, AP7802J, AP7811, AP7820, AP7821, AP7822, AP7850, AP7869, AP7899, AP7900, AP7901, AP7902, AP7902J, AP7911A, AP7920, AP7921, AP7922, AP7950, AP7968, AP7998

The replacement part numbers are as follows:

AP7152B, AP7155B, AP7175B, AP7800B, AP7801B, AP7802B, AP7802BJ, AP7811B, AP7820B, AP7821B, AP7822B, AP7850B, AP7869B, AP7899B, AP7900B, AP7901B, AP7902B, AP7902BJ, AP7911B, AP7920B, AP7921B, AP7922B, AP7950B, AP7968B, AP7998B

The following part numbers have been discontinued:

AP7851, AP7853, AP7823, AP7855A, AP7867A

We appreciate your patience during this transition. Additional technical information can be found on our website by searching for “Differences between AP7XXX and AP7XXXB Series Rack PDUs” under the Technical FAQ/Support section.

Sincerely,  
Ken Baer  
Product Manager – Rack Systems  
Schneider Electric

Schneider Electric

801 Corporate Centre Dr.  
O'Fallon, MO 63367  
Phone: 636-300-2300

[schneider-electric.com](http://schneider-electric.com)